



**NATIONAL
SAFETY APPAREL**

HYDROlite FR™ featuring GORE® PYRAD® fabric

Care & Maintenance Document

Cleaning HYDROlite FR™ garments regularly ensures optimum performance; oil, grease, and soil deposits can impair the fabric's protective performance. Follow the care instructions listed here and on the care label sewn into each garment. Failure to follow care instructions may result in voiding of the manufacturer's warranty.

CLEANING

- Close and cover all zippers and hook & loop fasteners to prevent damage
- Stain treatments may be used, test an area for color fastness & ensure the product is completely rinsed from the fabric
- Wash Separately from other garments
- Machine wash warm (max. 120°F/50°C) using mild detergent,
- Rinse 4 times (adding extra rinse to standard 3 rinse cycle) to remove all alkaline and detergent residues
- Do not use Chlorine Bleach or Hydrogen Peroxide Detergents (OxyClean)
- Do not use Fabric Softeners or Dryer sheets
- Turn garment inside out before putting it in the tumble dryer.
- Tumble Dry using Permanent Press Settings (Medium)
- Tumble Drying is recommended to protect the garments water repellent treatment
- Do Not Dry Clean HYDROlite FR™ Garments

STORAGE

- Do not store your garment in direct sunlight or near sources of UV light (to prevent color fading)
- Do not store your garment wet

REPAIRS

- Inspect Garments regularly for needed repairs
- National Safety Apparel® supports repairs of HYDROlite FR™ garments up to 5 years from purchase
- Contact National Safety Apparel® Customer Service to order repair service at 800-553-0672 or customerservice@thinknsa.com



GORE® PYRAD®
FABRIC

15825 Industrial Parkway, Cleveland, OH 44135
216.941.1111 800.553.0672 216.941.1130 Fax

www.thinkNSA.com